	Туре	Hits	Search Text	DBs	Time Stamp
1	IS&R	859	(219/117.1).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 14:34
2	IS&R	676	(228/119).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 10:20
3	IS&R	239	(29/402.01).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 10:41
4	IS&R	386	(29/402.18).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 10:42
5	IS&R	1234 71	("219").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 14:34
6	IS&R	4021 3	("228").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 14:34
7	IS&R	1814 08	("29").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 14:34
8	BRS	3308 96	\$5 or \$6 or \$7	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 14:34
9	BRS	1588	S8 and ((resistance or spot or seam or electrode\$1) near20 weld\$3) near200 (defect or repair or plug\$4 or hole or damage\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 14:36

	Туре	Hits	Search Text	DBs	Time Stamp
10	BRS	278	S8 and ((resistance or spot or seam or electrode\$1) near20 weld\$3) near200 (defect or repair or plug\$4 or hole or damage\$1) near200 (fill\$3 or slug or plug or nugget)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 14:40
11	BRS	277	•	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 14:40
12	BRS	251	•	DERWENT	2006/05/05 14:40

	Туре	Hits	Search Text	DBs	Time Stamp
13	BRS	218		US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 14:40
14	BRS	218	•	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 14:42
15	BRS	207		US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 14:42

	Туре	Hits	Search Text	DBs	Time Stamp
16	BRS	85	S8 and ((resistance or spot or seam or electrode\$1) near5 weld\$3) near50 (defect or repair or hole or damage\$1) near50 (fill\$3 or slug or plug)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 14:43
17	BRS	83	S8 and ((resistance or spot or seam or electrode\$1) near5 weld\$3) near50 (defect or repair or hole or damage\$1) near20 (fill\$3 or slug or plug)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 14:59
18	BRS	286	((resistance or spot or seam or electrode\$1) near5 weld\$3) near50 (defect or repair or hole or damage\$1) near20 (fill\$3 or slug or plug)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 14:59
19	BRS	348	· ·	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 15:00

	Туре	Hits	Search Text	DBs	Time Stamp
20	BRS	306	((resistance or spot or seam or electrode\$1) near5 weld\$3) near50 (defect or repair or hole or damage\$1) near20 (fill\$2 or slug or plug or consumable)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 15:00
21	BRS	267	((resistance or spot or electrode\$1) near5 weld\$3) near50 (defect or repair or hole or damage\$1) near20 (fill\$2 or slug or plug or consumable)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 15:00
22	BRS	210	((resistance or electrode\$1) near5 weld\$3) near50 (defect or repair or hole or damage\$1) near20 (fill\$2 or slug or plug or consumable)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 15:00
23	BRS	187	(detect or repair or hole or damage\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 15:00

	Туре	Hits	Search Text	DBs	Time Stamp
24	BRS	172	((resistance or electrode\$1) near5 weld\$3) near20 (defect or repair or hole or damage\$1) near10 (fill\$2 or slug or plug or consumable)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 15:01
25	BRS	153	((resistance or electrode\$1) near5 weld\$3) near20 (defect or repair or hole or damage\$1) near5 (fill\$2 or slug or plug or consumable)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 15:01
26	BRS	116	hole or damage\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 15:01
27	BRS	104	Idetect or repair or	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/05/05 15:01